

APX P25 Interfaced VR Firmware Release 1.71 – Release Notes

	New Version	Old Version
VR Application Software (4C083X11):	1.71	1.70
VR Boot Firmware (4C083X02):	1.60	1.60
VR BB DSP (4C083x04):	1.71	1.71
DVR/DVR-LX® TR DSP (4C083x03):	1.18	1.18
VRX1000 TR DSP (4C087x05):	1.07	1.07
Futurecom Repeater Configurator Software (6A083X06):	1.28	1.27

Note: New firmware and FRC software support all hardware platforms - DVR-LX®, DVR and VRX1000.

Compatible with following Motorola Radio Firmware Versions:

DVR	APX4000/6000/6500/7000/7500/8000/8500	R25.00.00 or later
DVR-LX®	APX4000/6000/6500/7000/7500/8000/8500	R25.00.00 or later
VRX1000	APX2500/4000/4500/5500/6000/6500/7000/7500/8000/8500	R25.00.00 or later

NOTE: Older MSU firmware is not compatible with this release - **MISMATCH ERROR** message will be displayed on control head. Please check Futurecom website for Compatibility Chart.

New Features / Enhancements:

- None

Issues fixed in this release:

- VR is on Forced Analog channel and Talkgroup Translation enabled: if MSU is switched from Analog to Digital P25 channel, PSU call is denied ^{DVR-935}
- No In Car Monitor (ICM) when MSU is Out-Of-Range and Local to System Call Upgrade is enabled ^{DVR-963}
- On Type II trunking system, if PSU can reach two Primary VRs, one of the Primary VRs may reattempt call handling causing loss of audio ^{DVR-949}
- After VR is deactivated by AVRA, VR activation by MSU Mode change may fail to activate VR ^{DVR-964}
- System Wide call from Local PSU via VR is not repeated locally ^{DVR-958}
- When MSU is operating through Smart Connect and DVR mode is set as Local, DVR repeats local call on selected MSU TG instead of System Wide talkgroup FFFF ^{DVR-1034}
- Duplicate ID triggered by Legacy PSU is not displayed on MSU CH ^{DVR-1020}
- NAC Linking feature fails to initialize a unique NAC after enabling feature for a channel. ^{DVR-1131}

Known issues in Firmware Release 1.71:

- None